

AD-A144 443


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
SCITICO DAM (CT 00529) (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV APR 80


1/1

UNCLASSIFIED

F/G 13/2

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A144 443

SCANTIC RIVER BASIN  
SCITICO, CONNECTICUT

SCITICO DAM  
CT 00529

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

This document has been approved  
for release and sale, its  
contents are unlimited.

APRIL 1980

84 08 20 025

DTIC  
ELECTED  
S AUG 20 1984

**UNCLASSIFIED**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER  CT 00529	2. GOVT ACCESSION NO. <i>A144443</i>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle)  Scitico Dam  NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED  INSPECTION REPORT
7. AUTHOR(s)  U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE April 1980
		13. NUMBER OF PAGES 50
		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
		16a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  DAMS, INSPECTION, DAM SAFETY, Scantic River Basin Scitico, Connecticut		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Scitico Dam is a run-of-the-river composite structure about 76 feet long and 22 feet high. The dam consists of a block masonry structure about 15 feet high capped with a rockfilled timber crib structure. The dam appears to be in fair condition. Scitico Dam has a maximum storage capacity of about 51 acre-feet and a maximum height of about 22 feet. Therefore, the dam is classified in the "Small" size category. The recommended range for the test flood for a "Small" size, "High" hazard dam is from 1/2 of the PMF to the full PMF.		

①

SCITICO DAM  
CT 00529

SCANTIC RIVER BASIN  
SCITICO, CONNECTICUT

DTIC  
ELE  
S AUG 20 1984  
A

<input checked="checked" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



This document has been approved  
for public release and sale; its  
distribution is unlimited.

L A-1

## NATIONAL DAM INSPECTION PROGRAM

Identification No:	CT 00529
Name of Dam:	Scitico Dam
Town:	Enfield
County and State:	Hartford, Connecticut
Stream:	Scantic River
Date of Inspection:	November 14, 1979

### BRIEF ASSESSMENT

Scitico Dam is a run-of-the-river composite structure about 76 feet long and 22 feet high. The dam consists of a block masonry structure about 15 feet high capped with a rockfilled timber crib structure. The dam crest, the width of which is not known, is covered with planking. A large mill building, presently used as an industrial laboratory, is adjacent to the right abutment wall of the dam. An abandoned hydropower facility at this site includes a penstock with a gated intake located a few feet to the right of the dam. The masonry section of the dam was constructed about 1890 and the cribbing was added in the late 1920's. The dam currently serves no useful purpose.

The dam appears to be in fair condition. No structural deficiencies were observed which would be indicative of an unsafe dam. However, a partial wash-out of the timber crib occurred in 1955 which suggests that the dam cannot withstand high river discharges. There is no functioning low-level outlet at this site although the hydropower penstock could possibly be used for partial reservoir drawdown.


Scitico Dam has a maximum storage capacity of about 51 acre-feet and a maximum height of about 22 feet. Therefore, the dam is classified in the "Small" size category. A large industrial building is located adjacent to the dam. A failure of Scitico Dam could cause flood waters to be directed into this building causing appreciable property damage and the possible loss of more than a few lives. Therefore, the dam is classified in the "High" hazard category. The recommended range for the test flood for a "Small" size, "High" hazard dam is from one-half of the Probable Maximum Flood (PMF) to the full PMF. The selected test flood for this structure is one-half of the PMF.

The test flood peak inflow to Scitico Dam was computed as 19,280 cfs. The routed test flood outflow of 19,070 cfs overtops the right abutment wall by 12.8 feet. The spillway is capable of discharging 3,350 cfs prior to overtopping of the right abutment wall (Elev. 144), which is about 18 percent of the routed test flood outflow.

Within one year after receipt of this Phase 1 inspection report, the Owner, Springbarn Lab Inc., should retain the services of a qualified registered professional engineer, experienced in the design and construction of dams, for the following purposes: 1) perform detailed hydrologic and hydraulic analyses in conjunction with structural stability analyses to assess the ability of the structure to withstand high flood flows; 2) study the suitability of the hydropower facilities as an outlet works and determine if additional outlet works should be provided; and 3) perform a detailed inspection of the dam during dry weather either with a low river discharge flowing over the dam or with the discharge diverted through the hydropower penstock.

In addition, the Owner should implement the following operational and maintenance procedures: 1) the operating condition of the sluice gate for the hydropower facility should be determined and the gate repaired, if necessary; 2) the branches and other debris hanging on the dam crest should be removed; 3) a program of annual technical inspection should be instituted; and 4) the formal surveillance plan, including round-the-clock monitoring during heavy precipitation, should be developed.

O'BRIEN & GERE ENGINEERS, INC.



Date 30 April 1980

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.



## TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

### REPORT

I. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose of Dam	1-2
h. Design and Construction History	1-2
i. Normal Operating Procedure	1-3
1.3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Damsite	1-3
c. Elevation	1-3
d. Reservoir	1-4
e. Storage	1-4
f. Reservoir Surface	1-4
g. Dam	1-4
h. Diversion and Regulating Tunnel	1-4
i. Spillway	1-5
j. Regulating Outlets	1-5

## TABLE OF CONTENTS (Con't)


<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-1
e. Downstream Channel	3-1
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-2
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

## TABLE OF CONTENTS (Con't)


<u>SECTION</u>	<u>PAGE</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Data	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
a. Operation and Maintenance Procedures	7-1
7.4 Alternatives	7-2

## APPENDICES

APPENDIX A - INSPECTION CHECKLIST	A-1 to A-4
APPENDIX B - ENGINEERING DATA	B-1 to B-2
APPENDIX C - PHOTOGRAPHS	C-1 to C-5
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-17
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



SCITICO DAM AS OBSERVED FROM IMMEDIATELY DOWNSTREAM. (11/14/79)



NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT  
SCITICO DAM

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, passed by Congress on August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate the National Program of Dam Inspections throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed were issued to O'Brien & Gere Engineers, Inc. by a letter from the Corps of Engineers dated November 6, 1979 and signed by Colonel William E. Hodgson, Jr. Contract No. DACW33-80-C-0014 has been assigned by the Corps of Engineers for this work.

b. Purpose of Inspection. The purpose of performing technical inspection and evaluation of non-federal dams is to:

1. Identify conditions which threaten public safety and make the Owner aware of any deficiencies to permit him to correct them in a timely manner.
2. Encourage and prepare the states to initiate effective dam safety programs for non-federal dams.
3. Update, verify, and complete the National Inventory of Dams.

1.2 Description of Project. (Information for this dam was obtained from the State of Connecticut, Department of Environmental Protection (DEP) and Springborn Lab, Inc.)

a. Location. Scitico Dam is located on the Scantic River in the Town of Enfield, Connecticut. An industrial laboratory located in a mill building adjacent to the right side of the dam is considered to be the major damage center. The Scantic River discharges into the Connecticut River about 11 miles downstream of the damsite. The dam is shown on the USGS Quadrangle entitled "Enfield, Conn." at coordinates N41°58.9', W72°31.1'. A regional location plan of Scitico Dam is enclosed as Figure 1, pg. vi.

b. Description of Dam and Appurtenances. Scitico Dam is a run-of-the-river composite structure about 76 feet long which is slightly arched in the upstream direction. The dam is about 22 feet high and consists of a 15-foot high block masonry base capped with a rock-filled timber crib structure. The dam crest appears to be covered with boards which have about a 5H:1V batter rising to the downstream face of the dam. The horizontal members of the timber cribbing are keyed into brick masonry abutment walls. The left abutment is a nearly vertical rock face rising about 30 feet above the dam crest. The right abutment forms part of the block masonry foundation for the two-story brick industrial building. The top of the abutment wall is about six feet above the dam crest, is tied into the building wall, and is estimated to be about 3.5 feet thick. (Refer to Page B-2).

An eight-foot wide intake structure with a wood gate is located between the right abutment wall and the mill building foundation. The intake is connected to a short 36-inch diameter penstock which conveys water to a small abandoned hydro-power turbine equipped with a mechanical power takeoff. The turbine has a vertical draft tube which directs flow into a tailrace downstream of the dam.

c. Size Classification. Scitico Dam has a maximum storage capacity of approximately 51 acre-feet and a maximum height of about 22 feet. The criteria for the "Small" size category includes dams which have between 50 and 1,000 acre-feet of storage capacity and are less than 40 feet high. Scitico Dam is therefore classified as a "Small" size dam.

d. Hazard Classification. Scitico Dam is located adjacent to a large, two-story building currently used as an industrial laboratory. The masonry foundation walls of this building function as river discharge training walls both upstream and downstream of the dam along the right side. It is evident that floodwaters resulting from a failure of Scitico Dam could cause excessive damage to the building and more than a few lives could possibly be lost. The dam is therefore classified as "High" hazard.

e. Ownership. The dam is owned by Springborn Lab Inc., Water Street, Enfield, CT 06082. Telephone: (203) 749-8371.

f. Operator. Mr. Ronald Miller of Springborn Lab Inc. is in charge of the dam and its appurtenances.

g. Purpose of Dam. The dam was constructed originally for industrial hydropower but currently has no useful purpose.

h. Design and Construction History. According to records provided by the DEP, the stone masonry section of Scitico Dam was constructed about 1890. The rockfilled timber crib was added in the late 1920's.

The State records indicate that a portion of the timber cribbing was washed out during the Hurricane Diane flood in August 1955. The damage was inspected by State officials and subsequently the owners contacted a registered professional engineer to design and supervise remedial repairs. The repairs consisted of replacing the washed out section of the timber cribbing, placing anchored reinforced concrete on a portion

of the masonry facing, repairing the crib anchor wall and facing and replacing fill in the cribbing. The work was completed in November 1955 and approved by State officials in April 1956.

i. Normal Operating Procedures. According to the Owner's representative, Mr. Ronald Miller, the sluice gate controlling discharge into the hydropower penstock is always closed. All river discharges are directed over the spillway portion of the dam.

### 1.3 Pertinent Data

a. Drainage Area. The drainage area for Scitico Dam encompasses approximately 64 square miles to the east-northeast of the site in Hartford and Tolland Counties in Connecticut and Hampden County in Massachusetts. Somersville Pond Dam, which impounds 40-acre Somerville Pond, located about 2.0 miles upstream, has a drainage area of about 60 square miles.

b. Discharge at Damsite.

1) Outlet Works. There is no functioning outlet facility at this site. If repaired, the hydropower penstock possibly could be used for partial reservoir drawdown.

2) Maximum Known Flood at Damsite. No flood records are maintained for the site; however, Hurricane Diane of August 1955 caused extensive damage to the dam. A flow of 15,400 cfs was recorded during August of 1955 at the community of Scitico, located immediately upstream of the dam.

3) Ungated Spillway Capacity at Top of Dam. The spillway capacity with reservoir level at the top of the right abutment wall, Elev. 144.0, is approximately 3,350 cfs.

4) Ungated Spillway Capacity at Test Flood Elevation. The spillway capacity with reservoir at test flood Elev. 156.8 is about 18,600 cfs.

5) Gated Spillway Capacity at Normal Pool. Not applicable.

6) Gated Spillway Capacity at Test Flood Elevation. Not applicable.

7) Total Spillway Capacity at Test Flood Elevation. Same as 4) above.

8) Total Project Discharge at Top of Dam. Same as 3) above.

9) Total Project Discharge at Test Flood. The combined discharge capacity of the flow over and around the dam at test flood Elev. 156.8 is about 19,070 cfs.

c. Elevation.(NGVD)

1. Streambed at Toe of Dam
2. Bottom of Cutoff

116.0±  
NA



3. Maximum Tailwater	Unknown
4. Normal Pool	138.0 <sup>+</sup>
5. Full Flood Control Pool	NA
6. Spillway Crest	138.0 <sup>+</sup>
7. Design Surge (Original Design)	Unknown
8. Top of Dam	138.0 <sup>+</sup>
9. Test Flood Surge	165.2 <sup>+</sup>
d. <u>Reservoir Length. (feet)</u>	
1. Normal Pool	3,000
2. Flood Control Pool	NA
3. Spillway Crest Pool	3,000
4. Top of Dam	3,000
5. Test Flood Pool	12,000
e. <u>Storage. (Acre-feet)</u>	
1. Normal Pool	51
2. Flood Control Pool	NA
3. Spillway Crest Pool	51
4. Top of Dam	51
5. Test Flood Pool	2,626
f. <u>Reservoir Surface. (Acres)</u>	
1. Normal Pool	7
2. Flood Control Pool	NA
3. Spillway Crest	7
4. Top of Dam	7
5. Test Flood Pool	202
g. <u>Dam.</u>	
1. Type	Composite block masonry capped with a rock filled timber crib
2. Length	76 feet
3. Height	22 feet
4. Top Width	Unknown
5. Side Slopes (upstream)	Unknown
(downstream)	Vertical
6. Zoning	Unknown
7. Impervious Core	Unknown
8. Cutoff	Unknown
9. Grout Curtain	Unknown
h. <u>Diversion and Regulating Tunnel.</u>	Not Applicable

i. Spillway. (The dam is an overflow structure and is not provided with additional spillway capacity.)

1. Type	Broad-crested timber weir
2. Length	76 feet
3. Crest Elevation	138.0 <sup>+</sup>
4. Gates	None
5. Upstream Channel	Scantic River
6. Downstream Channel	Scantic River

j. Regulating Outlets. There are no functioning regulating outlets at this site. If repaired, the hydropower penstock possibly could be used for partial reservoir drawdown.

## SECTION 2

### ENGINEERING DATA

#### 2.1 Design

Design data is unavailable for review of Scitico Dam. The principal design features for this dam are shown on the sketches enclosed in Appendix B.

#### 2.2 Construction

No information is available concerning construction at Scitico Dam other than that the gravity section was built about 1890 and the cribbing was added in the 1920's. Remedial repairs performed in 1955 are described in Section 1.2.h.

#### 2.3 Operation

Operational data is unavailable for this site.

#### 2.4 Evaluation

a. Availability. The information made available was obtained from the current Owner, Springborn Lab Inc., and DEP.

b. Adequacy. Information obtained during the field investigation and from conversations with the Owner's representative, combined with information from the DEP, is considered adequate for a Phase I assessment.

c. Validity. The information provided by the Owner's representative and the DEP appears to be valid.

SECTION 3  
VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Scitico Dam was performed on November 14, 1979. At the time of inspection, the reservoir water surface was about 2 inches above the dam crest. No underwater areas were inspected.

The observations and comments of the field inspection team are in the checklist which is Appendix A of this report.

b. Dam. The dam is considered to be in fair condition. River discharge at the time of inspection severely limited visual observations. Access to the right dam abutment is through a second-story window of the adjacent mill building. The dam crest boards were in-place and there was uniform flow over the dam crest. Tree branches and other debris were hanging on the dam crest (refer to Page C-1). There was no observable evidence of displacement of the timber cribbing, the rock fill or the stone blocks on the downstream face. The stone block masonry wall on the right side of the dam appeared to be in good condition with some minor loss of mortar between individual blocks. The brick masonry timber crib key wall was submerged at time of inspection. The nearly vertical rock abutment on the left side of the dam appears to be sound.

c. Appurtenant Structures. The wooden sluice gate, adjacent to the abutment on the right side of the dam which controls discharge to the hydropower penstock, was not operated during the inspection. The gate was completely submerged and could not be inspected. The wooden gate frame and steel operating mechanism appeared to be serviceable (refer to Page C-2).

Seepage estimated to be 15 gpm was discharging from around the penstock where it passes through the powerhouse foundation wall. The seepage spills onto the floor of the powerhouse and flows back into the river by way of the tailrace channel (refer to Page C-2). Inspection of the interior of the powerhouse was limited to the use of a flashlight since none of the light fixtures worked. It could not be determined if there was discharge from the draft tube.

d. Reservoir Area. The area surrounding the pond consists of moderate to steep, tree-covered slopes with numerous bedrock outcrops which rise 20 to 30 feet above normal pool elevation. A railroad bridge and highway bridge span the reservoir about 200 feet and 650 feet upstream of the dam, respectively.

e. Downstream Channel. The river channel is a steep narrow gorge no more than 200 feet wide for about 700 feet downstream of the dam beyond which the flood plain widens to about 0.2 miles. The channel is on an estimated one percent slope with heavily wooded banks.

### 3.2 Evaluation

The dam is considered to be in fair condition. The branches and other debris hanging on the dam crest should be removed. Further inspection of the dam is recommended during a period of low flow or with the discharge diverted through the hydropower penstock.

The sluice gate controlling flow to the hydropower penstock has never been operated by the current owners. If operable, it is the only means available for partial reservoir drawdown. Access to the sluice gate and dam is limited to a window in the adjacent mill building.

SECTION 4  
OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures.

a. General. Based on conversations with the Owner's representative, Mr. Ronald Miller, there are no operating procedures established for Scitico Dam.

b. Description of Any Warning System in Effect. According to Mr. Miller, no flood warning system is in effect at this site.

4.2 Maintenance Procedures

a. General. According to Mr. Miller, there is no maintenance performed on the dam.

b. Operating Facilities. According to Mr. Miller, the hydropower penstock has not been used by Springborn Lab, Inc.

4.3 Evaluation

There are no operational or maintenance procedures in effect at this site. Recommendations for improving these conditions are given in Section 7.3.

## SECTION 5

### EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

#### 5.1 General

The Scantic River upstream of Scitico Dam has an elongated watershed about 12 miles long and 5 miles wide. The eastern half of the basin is composed of forested, mountainous terrain. The western half of the watershed lies within the broad Connecticut River Valley. The topography consists of low-lying hills interspersed with marshes and swamps. The region is devoted to agriculture and contains a number of small towns and villages. Somersville Pond Dam is located on the Scantic River about 2.0 miles upstream of the Scitico Dam. The normal pool storage capacity and surface area of this reservoir are estimated to be 320 acre-feet and 40 acres, respectively.

#### 5.2 Design Data

Neither hydraulic nor hydrologic design data are available for Scitico Dam.

#### 5.3 Experience Data

There are no records of high reservoir pools or river discharges at this site. A portion of the timber cribbing was washed-out during hurricane Diane in August 1955. River discharges associated with this event are not available.

#### 5.4 Test Flood Analysis

The recommended test flood range for a "Small" size, "High" hazard dam is from one-half of the Probable Maximum Flood (PMF) to the full PMF. Due to the non-residential nature of the hazard area and the possibility that no lives would be lost during a breach flood, the selected test flood is one-half of the PMF.

Hydrologic and hydraulic calculations were performed with assistance of the HEC-1-DB computer program. The flood hydrographs were constructed from the Snyder unit hydrographs using Snyder coefficients which reflect the terrain of the drainage area, an initial infiltration of zero, and a constant loss rate of 0.05 inches per hour. The Hop Brook Adjustment Factor was used to reduce the Probable Maximum Precipitation based on the drainage area. Stage vs. discharge and stage vs. storage relationships were developed. The routing sequence consisted of dividing the watershed into a sub basin for each significant impoundment and routing the inflow hydrographs through each reservoir. The impoundments were assumed to be at their respective spillway crest elevations at the beginning of the storm event.

The test flood peak inflow to Scitico Reservoir was computed as 19,280 cfs. The routed test flood outflow of 19,070 cfs overtops the right abutment wall by 12.8 feet. The spillway is capable of discharging approximately 3,350 cfs prior to overtopping of the right abutment wall, which is about 18 percent of the routed test flood outflow.

### 5.5 Dam Failure Analysis

The primary hazard area is the Springborn Lab, Inc. building immediately adjacent to the right abutment of Scitico Dam. It is evident that a full or partial failure of the dam would direct breach discharges against the building, possibly causing excessive damage. More than a few lives could possibly be lost in the building. The first residential area is a single-family dwelling located about 1,350 feet downstream of the dam.

A failure of the dam was simulated by the HEC-1-DB computer program assuming a 76-foot wide by 22-foot deep breach with vertical side slopes developing within 30 minutes. The failure is assumed to occur with the reservoir surface at the top of the dam. The assumed breach would direct a flow of 2,250 cfs against the laboratory building. The breach flood was also routed to the first residential area and a flood water depth of 3.4 feet was computed at this location. A flood of this depth would be contained within the channel banks.



## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Visual Observations

There were no deficiencies observed during this visual inspection which suggest an unstable condition at Scitico Dam.

#### 6.2 Design and Construction Data

No information is available concerning the dam design or construction.

#### 6.3 Post Construction Changes

The remedial repairs performed on the dam following a partial wash-out of the timber cribbing in August 1955 during Hurricane Diane are described in Section 1.2.h. It is apparent, from the information describing this incident (available from the Connecticut DEP), that the dam probably cannot withstand very high river discharges.

#### 6.4 Seismic Stability

Scitico Dam is located in Seismic Zone 1 on the "Seismic Zone Map of Contiguous States". A dam located in Seismic Zone 1 need not be evaluated for seismic stability, according to the Recommended Guidelines for Phase I Dam Inspections.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

#### 7.1 Dam Assessment

a. Condition. The visual observations and review of the available information indicate that Scitico Dam is in fair condition. No structural deficiencies could be observed during the visual inspection which would render an unsafe assessment. However, a partial wash-out of the timber crib, during the Hurricane Diane flood in August 1955, suggests that the dam cannot withstand high river discharges. There is no functioning low level outlet provided at this site; although, the hydropower penstock if operable could be used for partial reservoir drawdown. The operating condition of the sluice gate controlling discharge into the penstock is unknown. Even if operable, the discharge capacity of the facility as an emergency outlet is restricted since flows must pass through the abandoned turbine.

b. Adequacy of Information. Information obtained during the field investigation and from conversations with the Owner's representative, combined with information from the DEP, is considered adequate for a Phase I assessment.

c. Urgency. Further investigations and remedial measures should be implemented within one year of receipt of this Phase I Inspection Report.

#### 7.2 Recommendations

It is recommended that the Owner, Springborn Lab, Inc., retain the services of a qualified, registered professional engineer for the following purposes:

1. Perform detailed hydrologic and hydraulic analyses in conjunction with structural stability analyses to assess the ability of the structure to withstand high flood flows.

2. Study the suitability of the hydropower facilities as an outlet works and determine if additional outlet works should be provided.

3. Perform a detailed inspection of the dam during dry weather either with a low river discharge flowing over the dam or with the discharge diverted through the hydropower penstock.

#### 7.3 Remedial Measures

a. Operation and Maintenance Procedures. The Owner should also implement the following operation and maintenance measures :

1. The operating condition of the hydropower penstock sluice gate should be determined and the gate repaired, if necessary. The tailrace should be cleared of any restrictions to flow.

2. The branches and other debris hanging on the dam crest should be removed.

3. A program of annual technical inspection should be instituted.

4. A formal surveillance plan, including round-the-clock monitoring during heavy precipitation, should be developed.

#### 7.4 Alternatives

As an alternative to the above recommendations and remedial measures, the dam could be breached and the impoundment drained.

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
INSPECTION TEAM ORGANIZATION

Project: SCITICO DAM  
National I.D. #: CT 00529  
Location: Enfield, CT  
Type of Dam: Composite - masonry and timber crib  
Inspection Date(s): November 14, 1979  
Weather: Overcast, 40°  
Pool Elevation: 138.2 ± MSL

Inspection Team

Leonard Beck	O'Brien & Gere	Structures
Steven Snider	O'Brien & Gere	Foundations & Materials
Alan Hanscom	O'Brien & Gere	Structures
Rodney Georges	Bryant & Associates	Hydrology/Hydraulics

\*Mr. John J. Williams, Vice-President, O'Brien & Gere has visited the site but not necessarily in conjunction with the inspection team.

Owner's Representative

Mr. Ronald Miller  
\_\_\_\_\_

# VISUAL INSPECTION CHECK LIST

Project: SCITICO DAM

National I.D. #: CT 00529

Date(s): November 14, 1975

AREA EVALUATED	CONDITIONS
<u>CONCRETE/MASONRY DAM</u>	
Crest Elevation	Timber Crib - 138.0
Current Pool Elevation	138.2 ±
Maximum Impoundment to Date	Unknown.
Any Noticeable Seepage	Obscured by over-flow.
Conditions of Abutment	Left abutment is a rock slope. Masonry on right abutment showed some minor loss of joint material.
Drains	None.
Water Passages	None.
Foundation	Submerged. Assumed to be bedrock.
Masonry/Concrete Surface Cracks	None.
Structural Cracking	None.
Vertical and Horizontal Alignment	Good.
Monolith Joints	Obscured by over-flow.
Construction Joints	Obscured by over-flow.
Upstream Embankment	None.
Instrumentation System	None.
Inspection Galleries	None.

# VISUAL INSPECTION CHECK LIST

Project: SCITICO DAM

National I.D. #: CT 00529

Date(s): November 14, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	
General Condition	Timber crest planks appear to slope up to downstream dam crest
Loose Rock Overhanging Channel	None.
Trees Overhanging Channel	None.
Floor of Approach Channel	Scantic River bottom.
b. Weir and Training Walls	
General Condition of Concrete	Masonry foundation walls of adjacent bldg. in fair condition.
Rust or Staining	None.
Spalling	Some loss of mortar.
Any Visible Reinforcing	N/A
Any Seepage or Efflorescence	N/A
Drain Holes	None.
c. Discharge Channel	
General Condition	Good. Appeared to be some scour of river bed at toe of dam.
	A-3

# VISUAL INSPECTION CHECK LIST

Project: SCITICO DAM

National I.D. #: CT 00529

Date(s): November 14, 1979

AREA EVALUATED	CONDITIONS
<u>HYDROPOWER FACILITIES -</u>	
Approach Channel	Scantic River
Training Walls	Industrial building masonry foundation wall.
Intake Structure	Wood frame sluice gate - 8 ft. wide. Gate has been closed since current owner's acquisition of property.
Penstock	~36" $\phi$ Steel or cast iron. Seepage of about 15 gpm. flowing from around conduit where it passes through wall.
Turbine(s)	One horizontal-blade turbine equipped with mechanical take-off. Heavily corroded and not in use.
Power house	Inspection performed with flashlight. Floor carrying seepage discharge.
Tailrace	Sheet steel doors over exit portals. One door open to release seepage. Channel invert clogged with debris. Training wall in fair condition.



APPENDIX B

ENGINEERING DATA

SUBJECT	SCITICO DAM	SHEET	BY	DATE	JOB NO
---------	-------------	-------	----	------	--------


APPENDIX B  
ENGINEERING DATA  
TABLE OF CONTENTS

SITE PLAN

PAGE  
B-1


UPSTREAM PROFILE

B-2



SITE PLAN  
SCITICO DAM

CT 00529



# UPSTREAM PROFILE SCITICO DAM

CT 00529

*Note: Sketch prepared from visual inspection and recorded observations made during remedial repairs in 1955.*

APPENDIX C

PHOTOGRAPHS

APPENDIX C  
SELECTED PHOTOGRAPHS OF PROJECT

LOCATION PLAN

Site Plan

Page  
No.

A

PHOTOGRAPHS

No.

Page  
No.

1. Left abutment of the dam which is nearly vertical exposed bedrock.
2. Vertical rock abutment immediately downstream of the dam.
3. Hoisting mechanism for the slice gate which controls flow to the penstock leading to a turbine which has been out of service for many years.
4. Tailrace for the out of service turbine.
5. Impoundment immediately upstream of the dam.
6. River conditions immediately downstream of the dam.

1


1

2

2


3

3



PLAN  
SCITICO DAM

CT 00529



1. LEFT ABUTMENT OF THE DAM WHICH IS NEARLY VERTICAL EXPOSED BEDROCK. (11/14/79)



2. VERTICAL ROCK ABUTMENT IMMEDIATELY DOWNSTREAM OF THE DAM. (11/14/79)





3. HOISTING MECHANISM FOR THE SLUICE GATE WHICH CONTROLS FLOW TO THE PENSTOCK LEADING TO A TURBINE WHICH HAS BEEN OUT OF SERVICE FOR MANY YEARS. (11/14/79)



4. TAILRACE FOR THE OUT OF SERVICE TURBINE. (11/14/79)



5. IMPOUNDMENT IMMEDIATELY UPSTREAM OF THE DAM. (11/14/79)



6. RIVER CONDITIONS IMMEDIATELY DOWNSTREAM OF THE DAM. (11/14/79)

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS


SUBJECT	SHEET	BY	DATE	JOB NO
SCITICO DAM				

## APPENDIX D

### HYDROLOGIC & HYDRAULIC COMPUTATIONS

#### TABLE OF CONTENTS

	<u>PAGE</u>
REGIONAL VICINITY MAP, FIGURE 1	D-1
SURFACE AREA DATA, PMP DATA, $T_p$ COMPUTATIONS SCITICO DAM	D-2
$T_p$ COMPUTATIONS SOMERVILLE POND, SPWY. & DAM PROFILE SCITICO	D-3
SPWY. & DAM PROFILE SOMERVILLE PD., STAGE-DISCHARGE SCITICO DAM	D-4
STAGE-DISCHARGE & STAGE-STORAGE SCITICO DAM	D-5
STAGE-DISCHARGE SOMERVILLE PD., SECTION PROFILE HAZARD AREA	D-6
HEC-1 DAM SAFETY VERSION COMPUTER OUTPUT NO BREACH	D-7 to D-13
HEC-1 DAM SAFETY VERSION COMPUTER OUTPUT COMPLETE BREACH	D-14 to D-17



SUBJECT	SHEET	BY	DATE	JOB NO
SCITICO DAM - H&H	D-2	SHS	3/3/80	2060-001

## HYDROLOGIC & HYDRAULIC CALCULATIONS

Total Drainage Area : 64 sq.mi.

Somersville Pond Sub-basin Area: 60 sq.mi. (.20 miles u/s of Scitico Dam)

Scitico Dam Subdrainage Area : 4 sq.mi.

SCITICO RESERVOIR AREA @ EL. 116 (BOTTOM OF DAM) = 0 ACRES

Scitico Res. Area @ Top of Dam El. 138 = 7 acres (Normal Pool)

Scitico Res. Area @ El. 140 = 28 acres

Scitico Res. Area @ El. 150 = 77 acres

Scitico Res. Area @ El. 160 = 153 acres

SCITICO RES. AREA @ EL. 170 = 248 ACRES

Somersville Pond Area @ El. 180 = 40 acres (Normal Pool)

Somersville Pond Area @ El. 190 = 440 acres

SOMERSVILLE POND AREA @ EL. 200 = 1,550 ACRES

### PMP DATA

The 24 hr., 200 sq.mi. Index Rainfall is 21.1 inches

Ref: HMS Report #33

6 hr. % = 89 %

12 hr. % = 105 %

24 hr. % = 113 %

48 hr. % = 120 %

### $T_p$ Computations - Scitico Dam

Snyder Coefficients:

$$T_p = C_t (L L_{ca})^{0.3}$$

$$C_t = 2.5$$

$$L = 4.9 \text{ miles}$$

$$C_p = 0.5$$

$$L_{ca} = 1.5 \text{ miles}$$

$$T_p = 2.5 (4.9 \times 1.5)^{0.3} \approx 4.5 \text{ hours}$$

SUBJECT	SHEET	BY	DATE	JOB NO.
SCITICO DAM - H & H	D-3	SHS	3/3/80	2060-001

Tp Computations - Somersville Pond

$$C_t = 3.0$$


$$C_p = 0.5$$

$$L = 12.9 \text{ miles}$$

$$L_{ca} = 3.5 \text{ miles}$$


$$T_p = 3.0 (12.9 \times 3.5)^{0.3} \approx 9.4 \text{ hours}$$

Spillway & Dam Profile: Scitico



SUBJECT	SHEET	BY	DATE	JOB NO.
SCITICO DAM - H & H	D-4	SHS	3/20/80	2060-001

SPILLWAY & DAM PROFILE : SOMERSVILLE POND




STAGE-DISCHARGE → SCITICO DAM

$Q = CLH^{3/2} \rightarrow C_{DAM} = 3.0, L_{DAM} = 76 \text{ FT.}; C = 2.8 \text{ (AROUND BUILDING, OVER BUILDING, OVER ABUTMENTS)}$

ELEV.	OVER DAM		AROUND BUILDING			OVER BUILDING			OVER ROCK ABUTMENT			Q <sub>TOTAL</sub>
	H (FT.)	Q (CFS)	H (FT.)	L <sub>EFF.</sub> (FT.)	Q (CFS)	H (FT.)	L (FT.)	Q (CFS)	H (FT.)	L <sub>EFF.</sub> (FT.)	Q (CFS)	
138	0	0										0
139	1	228										228
140	2	645										645
142	4	1,824										1,824
144		3,351										3,351
146	8	5,159										5,159
148	10	7,210										7,210
150	12	9,478										9,478
155	17	15,981	0	0	0							15,981
160	22	23,527	5	30	939							24,466
165	27	31,987	10	60	5,313	0	60	0	0	0	0	37,300
170	32	41,272	15	90	14,640	5	60	1,878	5	20	626	58,416



SUBJECT	SHEET	BY	DATE	JOB NO
SCITICO DAM - H&H	D-5	SHS	3/27/80	2060-001



STORAGE - A.F.

SUBJECT	SHEET	BY	DATE	JOB NO
SCITICO DAM - H&H	D-6	SHS	3/20/80	2060-001


STAGE-DISCHARGE → SOMERSVILLE POND DAM

$$Q = CLH^{3/2} \rightarrow C_{\text{spill.}} = 3.1, L = 100 \text{ FT.}; C_{\text{dam}} = 2.9, L \text{ VARIES - BASE } L = 300 \text{ FT.}$$

ELEVATION NGVD	HEAD (Spillway) ft.	Q (Spillway) (C=3.1)	H (DAM) FT.	EFFECTIVE LENGTH OF DAM FT.	Q (Dam) (C=2.9)	TOTAL DISCHARGE CFS
180 Spillway Crest	0	0	-	300	-	0
181	1	310	-	300	-	310
182	2	877	-	300	-	877
183 Dam Crest	3	1611	0	300	-	1611
184	4	2480	1	325	943	3423
185	5	3466	2	350	2871	6337
190	10	9803	7	475	25,512	35,315
200	20	27,727	17	800	162,615	190,342

HAZARD AREA - 1,350 feet Downstream

SECTION PROFILE



MANNING'S COEFFICIENTS: RIVER - 0.030  
OVERBANKS - 0.060

River Slope = 0.01 ft/ft

D-6

---

D-7

FLUW HYDROGRAPH PACKAGE (HEC-1)  
DAY SAFETY VERSION JULY 1978

NAME: 03427400  
TIME: 12.20.42.

HYDROLOGIC ANALYSIS OF SCIFIC DAM  
NAME: 03427400  
NEW ENGLAND DIVISION - CORPS OF ENGINEERS

JOH-SPECIFICATION

NO	NH	IMIN	IDAY	IMIN	METRC	IPLT	IPRT	NSTAN
300	0	30	0	0	0	0	-4	0

MULTI-PLAN ANALYSES TO BE PERFORMED

WPLAN= 1 NRTIN= 9 LRTIO= 1

PERCENTAGES OF RME 10 20 30 40 50 60 70 80 90 100

ANALOG HYDROGRAPH DEVELOPMENT FOR SOMERSVILLE BOND

SUM-AHEA-TUNOFF-COMPUTATION

INFLOW TO S04EPSVILLE POND

ISTAN	ICOMP	IFCOH	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
S04ERS	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IMVNS	IUMG	IAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	10.00	0.00	0.00	0.00	0.00	0.00	0	1	0

PRECIP DATA

DATE	PWS	W	W12	W24	W72	Q46
0.00	21.10	89.00	105.00	113.00	120.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .856

LOSS DATA

LRPRT	STARR	ULFKN	MTIOL	FRAIN	STORS	RTIOK	STRTL	CHSTL	ALSKA	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	0.00	0.00	0.00

UNIT HYDROGRAPH DATA

WPLAN= 1 NRTIN= 9 LRTIO= 1

RECESSION DATA

WPLAN= 1 NRTIN= 9 LRTIO= 1

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES LAGS 9.39 MONTHS, CP= .50 VOL= .97

DATE	1471	1500	1530	1560	1590	1620	1650	1680	1710	1740	1770	1800	1830	1860	1890	1920	1950	1980	2010	2040	2070	2100	2130	2160	2190	2220	2250	2280	2310	2340	2370	2400	2430	2460	2490	2520	2550	2580	2610	2640	2670	2700	2730	2760	2790	2820	2850	2880	2910	2940	2970	3000	3030	3060	3090	3120	3150	3180	3210	3240	3270	3300	3330	3360	3390	3420	3450	3480	3510	3540	3570	3600	3630	3660	3690	3720	3750	3780	3810	3840	3870	3900	3930	3960	3990	4020	4050	4080	4110	4140	4170	4200	4230	4260	4290	4320	4350	4380	4410	4440	4470	4500	4530	4560	4590	4620	4650	4680	4710	4740	4770	4800	4830	4860	4890	4920	4950	4980	5010	5040	5070	5100	5130	5160	5190	5220	5250	5280	5310	5340	5370	5400	5430	5460	5490	5520	5550	5580	5610	5640	5670	5700	5730	5760	5790	5820	5850	5880	5910	5940	5970	6000	6030	6060	6090	6120	6150	6180	6210	6240	6270	6300	6330	6360	6390	6420	6450	6480	6510	6540	6570	6600	6630	6660	6690	6720	6750	6780	6810	6840	6870	6900	6930	6960	6990	7020	7050	7080	7110	7140	7170	7200	7230	7260	7290	7320	7350	7380	7410	7440	7470	7500	7530	7560	7590	7620	7650	7680	7710	7740	7770	7800	7830	7860	7890	7920	7950	7980	8010	8040	8070	8100	8130	8160	8190	8220	8250	8280	8310	8340	8370	8400	8430	8460	8490	8520	8550	8580	8610	8640	8670	8700	8730	8760	8790	8820	8850	8880	8910	8940	8970	9000	9030	9060	9090	9120	9150	9180	9210	9240	9270	9300	9330	9360	9390	9420	9450	9480	9510	9540	9570	9600	9630	9660	9690	9720	9750	9780	9810	9840	9870	9900	9930	9960	9990	10000
1471	1500	1530	1560	1590	1620	1650	1680	1710	1740	1770	1800	1830	1860	1890	1920	1950	1980	2010	2040	2070	2100	2130	2160	2190	2220	2250	2280	2310	2340	2370	2400	2430	2460	2490	2520	2550	2580	2610	2640	2670	2700	2730	2760	2790	2820	2850	2880	2910	2940	2970	3000	3030	3060	3090	3120	3150	3180	3210	3240	3270	3300	3330	3360	3390	3420	3450	3480	3510	3540	3570	3600	3630	3660	3690	3720	3750	3780	3810	3840	3870	3900	3930	3960	3990	4020	4050	4080	4110	4140	4170	4200	4230	4260	4290	4320	4350	4380	4410	4440	4470	4500	4530	4560	4590	4620	4650	4680	4710	4740	4770	4800	4830	4860	4890	4920	4950	4980	5010	5040	5070	5100	5130	5160	5190	5220	5250	5280	5310	5340	5370	5400	5430	5460	5490	5520	5550	5580	5610	5640	5670	5700	5730	5760	5790	5820	5850	5880	5910	5940	5970	6000	6030	6060	6090	6120	6150	6180	6210	6240	6270	6300	6330	6360	6390	6420	6450	6480	6510	6540	6570	6600	6630	6660	6690	6720	6750	6780	6810	6840	6870	6900	6930	6960	6990	7020	7050	7080	7110	7140	7170	7200	7230	7260	7290	7320	7350	7380	7410	7440	7470	7500	7530	7560	7590	7620	7650	7680	7710	7740	7770	7800	7830	7860	7890	7920	7950	7980	8010	8040	8070	8100	8130	8160	8190	8220	8250	8280	8310	8340	8370	8400	8430	8460	8490	8520	8550	8580	8610	8640	8670	8700	8730	8760	8790	8820	8850	8880	8910	8940	8970	9000	9030	9060	9090	9120	9150	9180	9210	9240	9270	9300	9330	9360	9390	9420	9450	9480	9510	9540	9570	9600	9630	9660	9690	9720	9750	9780	9810	9840	9870	9900	9930	9960	9990	10000	

UNITED STATES COMPUTING SYSTEMS, INC.

END-OF-PERIOD FLOW

WPLAN= 1 NRTIN= 9 LRTIO= 1

SUM= 21.67-19.01-1.77-1512457.  
( 551.1 ( 506.1 ( 45.1 ( 42420.01)

.....

HYDROGRAPH ROUTING

~~ROUTING DATA FROM SOMERSVILLE DAM~~

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

## SUB-AREA PINOFF COMPUTATION

INFLW TO SCITICO LESS SOMERSVILLF

ISTAO	ICOMM	IECON	ITIME	JPLY	JPNY	INAME	ISTAGE	IAUTO
0	0	0	0	0	0	1	0	0
CITICO								

HYDROGRAPH DATA									
INHYDG	IUMG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	4.00	0.00	64.00	0.00	0.000	0	1	0

	PRECIP DATA							
	SPFE	PWS	R6	R12	R24	K48	A72	R96
0-0.01	0.00	21.10	01.00	105.00	113.00	120.00	0.00	0.00

INSPC COMPILED BY THE PROGRAM IS .1156

CNS-Data										
CHOP	STKR	OLTK	NTOL	EMAN	STKS	RTOK	STAL	CNSTL	ALSHX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00

UNIT -HYDROGRAPH DATA  
TYPE 4.50 CP= .50 NTA= 0

```

RECESSION DATA
SINIQUE= -1.70  QHCSN= -.10  RTIOR= 2.00

```

INIT WINDING GRAPH TO END-OF-PERIOD UNITERATES, LAG=										4.54 HOURS, CP=		.50 VOL= 1.00	
10.	36.	73.	117.	165.	212.	250.	277.	291.	289.				
20.	50.	100.	150.	200.	250.	277.	291.	289.	130.				
30.	75.	150.	225.	300.	375.	450.	525.	600.	675.				
40.	100.	200.	300.	400.	500.	600.	700.	800.	900.				
50.	125.	250.	375.	500.	625.	750.	875.	1000.	1125.				
60.	150.	300.	450.	600.	750.	900.	1050.	1200.	1350.				
70.	175.	350.	525.	700.	875.	1050.	1225.	1400.	1575.				
80.	200.	400.	600.	800.	1000.	1200.	1400.	1600.	1800.				
90.	225.	450.	675.	900.	1125.	1350.	1575.	1800.	2025.				
100.	250.	500.	750.	1000.	1250.	1500.	1750.	2000.	2250.				
110.	275.	550.	825.	1100.	1375.	1650.	1925.	2200.	2475.				
120.	300.	600.	900.	1200.	1500.	1800.	2100.	2400.	2700.				
130.	325.	650.	975.	1300.	1625.	1950.	2275.	2600.	2925.				
140.	350.	700.	1050.	1400.	1750.	2100.	2450.	2800.	3150.				
150.	375.	750.	1125.	1500.	1875.	2250.	2625.	3000.	3375.				
160.	400.	800.	1200.	1600.	2000.	2400.	2800.	3200.	3600.				
170.	425.	850.	1275.	1700.	2125.	2550.	2975.	3400.	3825.				
180.	450.	900.	1350.	1800.	2250.	2700.	3150.	3600.	4050.				
190.	475.	950.	1425.	1900.	2375.	2850.	3325.	3840.	4350.				
200.	500.	1000.	1500.	2000.	2500.	3000.	3500.	4000.	4500.				
210.	525.	1050.	1575.	2100.	2625.	3150.	3675.	4200.	4725.				
220.	550.	1100.	1650.	2200.	2750.	3300.	3850.	4440.	5000.				
230.	575.	1150.	1725.	2300.	2875.	3450.	4025.	4680.	5250.				
240.	600.	1200.	1800.	2400.	3000.	3600.	4200.	4920.	5550.				
250.	625.	1250.	1875.	2500.	3125.	3750.	4375.	5160.	5850.				
260.	650.	1300.	1950.	2600.	3250.	3900.	4550.	5400.	6150.				
270.	675.	1350.	2025.	2700.	3375.	4050.	4725.	5640.	6450.				
280.	700.	1400.	2100.	2800.	3500.	4200.	4900.	5880.	6750.				
290.	725.	1450.	2175.	2900.	3625.	4350.	5075.	6120.	7050.				
300.	750.	1500.	2250.	3000.	3750.	4500.	5250.	6360.	7350.				
310.	775.	1550.	2325.	3100.	3875.	4650.	5425.	6600.	7650.				
320.	800.	1600.	2400.	3200.	4000.	4800.	5600.	6840.	7950.				
330.	825.	1650.	2475.	3300.	4125.	4950.	5775.	7080					

	N	MO DA	HR MN	PERIOD	RATN	FACS	LOSS	END-OF-PERIOD FLOW COMP D	MO DA	HR MN	PERIOD	RAIN	EJCS	LOSS	COMP Q
--	---	-------	-------	--------	------	------	------	------------------------------	-------	-------	--------	------	------	------	--------

SUM	21.67	19.91	1.77	103743.
-----	-------	-------	------	---------

COMBINING SOMERSVILLE POND ROUTED OUTFLOW AND SCLTICO DAM RUNOFF

CVMM 192-PT11908105

## COMBINE HYDROGRAPHS

ISTAT	ICOMP	IECON	ITAPE	JPLT	JPHY	INAMF	ISTAGE	IAUTO
0	0	0	0	0	0	1	0	0

**UNITED COMPUTING SYSTEMS, INC.**

REQUIRED OUTFLOW FROM SCITCO DAM

LFTH	LEUM	ICEON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
SCILIC	1	0	0	0	0	1	0	0

ROUTING DATA									
WCLASS	CLASS	AVG	POES	ISAME	IPPT	IPMA	LSR		
0-0	0-000	0-0/0	1	1	0	0	0		

WSTAS	WSTOL	LAS	WSTHK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-138.	-1

00-001 00-001 00-001 00-001 00-001

228.00	445.00	1026.00	3351.00	5159.00	7210.00
1416.00					

1.	24.	77.	153.	249.
----	-----	-----	------	------

STAGE-STORAGE DATA FOR SCUTCO DAM			
51.	84.	589.	3703.
		1717.	

144.	140.	150.	160.	170.)
CHL	5000	5000	5000	5000
EXP	EXP	EXP	EXP	EXP

[illegible]

	TOPEL	COORD	EXPO	DAMWID
TOP OF DAM ELEVATION →	138.0	0.0	0.0	0.0

0.1 ANF  
PEAK OUTFLOW IS 3A05. AT TIME 49.50 HOURS

0.2 AMF  
PEAK OUTFLOW IS 7667. AT TIME 69.50 HOURS

0.3 AMF  
PEAK INTENSITY IS 11490. AT TIME 44.50 MINUS

0.4 AMF

0.5 PMF

PEAK OUTFLOW IS 1906%. AT TIME 49.5" HOURS

PEAK OUTFLOW IS 22773. AT TIME 49.50 HOURS

0-7-PMF  
PEAK OUTFLOW IS 24655. AT TIME 49.50 HOURS

0.8 PMF  
PEAK OUTFLUX IS 30345. AT TIME 49.50 HOURS

AMP  
BEAK UNFIELD IS 30035. AT TIME 49.50 HOURS

LEARN YOURS TO

0-11

PEAK FLOW AND STORAGE (END OF PERTURB) SUMMARY FOR MULTIPLE PLAN-RATIO-PERMANENT COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5 RATIO 6 RATIO 7 RATIO 8 RATIO 9

HYDROGRAPH AT SOMEWHERE	60.00	1	3634.	7268.	10902.	14536.	18170.	21804.	25439.	29072.	36340.
	( 155.40)		( 102.40)	( 205.81)	( 308.71)	( 411.62)	( 514.52)	( 617.42)	( 720.33)	( 823.23)	( 1029.04)
ROUTED TO POND	40.00	1	3600.	7244.	10862.	14473.	18074.	21663.	25236.	28791.	36152.
	( 155.40)		( 101.43)	( 205.14)	( 307.57)	( 409.82)	( 511.80)	( 613.43)	( 714.81)	( 815.27)	( 1023.72)
HYDROGRAPH AT CITICO	4.00	1	430.	859.	1289.	1718.	2148.	2577.	3007.	3436.	4295.
	( 10.36)		( 12.16)	( 24.32)	( 36.49)	( 48.65)	( 60.81)	( 72.97)	( 85.14)	( 97.30)	( 121.62)
2 COMBINED TOTAL	44.00	1	3834.	7745.	11603.	15448.	19276.	23085.	26879.	30668.	38492.
	( 145.76)		( 104.54)	( 219.30)	( 328.57)	( 437.43)	( 545.84)	( 653.69)	( 761.13)	( 868.43)	( 1090.17)
ROUTED TO SCITIC	44.00	1	3805.	7667.	11490.	15245.	19066.	22773.	26455.	30395.	38035.
	( 145.76)		( 107.75)	( 217.11)	( 325.36)	( 431.69)	( 539.89)	( 644.87)	( 754.79)	( 860.69)	( 1077.02)

TEST FLOOD PEAK INFLOW

ROUTED TEST FLOOD OUTFLOW



# SUMMARY OF DAM SAFETY ANALYSIS

## FLOOD RESULTS AT SOMERSVILLE POND DAM

ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
0.	180.00	180.00	183.00
0.	0.	0.	223.
0.	0.	0.	161.

Ratio OF P-F	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME-OF MAX OUTFLOW HOURS	TIME-OF FAILURE HOURS
.10	184.06	1.06	363.	3600.	17.50	49.00	0.00
.20	185.16	2.10	551.	7244.	28.50	49.00	0.00
.30	185.74	2.70	679.	10462.	35.50	49.00	0.00
.40	186.40	3.40	824.	14473.	40.00	49.00	0.00
.50	187.03	4.03	986.	18074.	43.50	49.00	0.00
.60	187.64	4.64	1167.	21663.	46.50	49.00	0.00
.70	188.26	5.26	1366.	25236.	49.00	49.00	0.00
.80	188.87	5.87	1585.	28791.	50.50	49.00	0.00
1.00	189.93	7.05	2066.	36152.	54.00	49.00	0.00

TEST FLOOD ELEVATION FOR SOMERSVILLE POND  
 TEST FLOOD ROUTED  
 OUTFLOW FROM SOMERSVILLE POND

# SUMMARY OF DAM SAFETY ANALYSIS

## TEST FLOOD RESULTS AT SCITIGO DAM

ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
0.	139.00	139.00	136.00
0.	51.	51.	51.
0.	0.	0.	0.

Ratio OF P-F	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME-OF MAX OUTFLOW HOURS	TIME-OF FAILURE HOURS
.10	144.50	6.50	251.	3805.	150.00	49.50	0.00
.20	145.40	10.40	473.	7667.	150.00	49.50	0.00
.30	146.25	13.55	716.	11490.	150.00	49.50	0.00
.40	146.93	16.43	996.	15245.	150.00	49.50	0.00
.50	147.42	19.42	1274.	19046.	150.00	49.50	0.00
.60	147.88	21.88	1564.	22773.	150.00	49.50	0.00
.70	148.45	22.85	1851.	26655.	150.00	49.50	0.00
.80	149.11	24.31	2093.	30395.	150.00	49.50	0.00
1.00	150.17	27.17	2664.	39075.	150.00	49.50	0.00

TEST FLOOD ELEVATION  
 TEST FLOOD ROUTED OUTFLOW

FLOOD HYDROGRAPH WACKRAF (MFC-1)  
 DAY SAFETY VERIFICATION JULY 1978  
 CASE IDENTIFICATION 24-119-99

SCITICO DAM BREACH OUTFLOW TO SECONDARY DAMAGE CENTER

INPUT

HYDROLOGIC ANALYSIS OF SCITICO DAM

NATIONAL SAFETY PROGRAM

NEW ENGLAND DIVISION - CORPS OF ENGINEERS

1 1 1 1 1  
 2 1 1 1 1  
 3 1 1 1 1  
 4 1 1 1 1  
 5 1 1 1 1  
 6 1 1 1 1  
 7 1 1 1 1  
 8 1 1 1 1  
 9 1 1 1 1  
 10 1 1 1 1  
 11 1 1 1 1  
 12 1 1 1 1  
 13 1 1 1 1  
 14 1 1 1 1  
 15 1 1 1 1  
 16 1 1 1 1  
 17 1 1 1 1  
 18 1 1 1 1  
 19 1 1 1 1  
 20 1 1 1 1  
 21 1 1 1 1  
 22 1 1 1 1  
 23 1 1 1 1  
 24 1 1 1 1  
 25 1 1 1 1  
 26 1 1 1 1  
 27 1 1 1 1  
 28 1 1 1 1

ROUTED OUTFLOW FROM SCITICO DAM

1 130 140 150 155 160  
 2 130 140 150 155 160  
 3 130 140 150 155 160  
 4 130 140 150 155 160  
 5 130 140 150 155 160  
 6 130 140 150 155 160  
 7 130 140 150 155 160  
 8 130 140 150 155 160  
 9 130 140 150 155 160  
 10 130 140 150 155 160  
 11 130 140 150 155 160  
 12 130 140 150 155 160  
 13 130 140 150 155 160  
 14 130 140 150 155 160  
 15 130 140 150 155 160  
 16 130 140 150 155 160  
 17 130 140 150 155 160  
 18 130 140 150 155 160  
 19 130 140 150 155 160  
 20 130 140 150 155 160  
 21 130 140 150 155 160  
 22 130 140 150 155 160  
 23 130 140 150 155 160  
 24 130 140 150 155 160  
 25 130 140 150 155 160  
 26 130 140 150 155 160  
 27 130 140 150 155 160  
 28 130 140 150 155 160

SCITICO DAM BREACH TO MAZARD AREA

1 130 140 150 155 160  
 2 130 140 150 155 160  
 3 130 140 150 155 160  
 4 130 140 150 155 160  
 5 130 140 150 155 160  
 6 130 140 150 155 160  
 7 130 140 150 155 160  
 8 130 140 150 155 160  
 9 130 140 150 155 160  
 10 130 140 150 155 160  
 11 130 140 150 155 160  
 12 130 140 150 155 160  
 13 130 140 150 155 160  
 14 130 140 150 155 160  
 15 130 140 150 155 160  
 16 130 140 150 155 160  
 17 130 140 150 155 160  
 18 130 140 150 155 160  
 19 130 140 150 155 160  
 20 130 140 150 155 160  
 21 130 140 150 155 160  
 22 130 140 150 155 160  
 23 130 140 150 155 160  
 24 130 140 150 155 160  
 25 130 140 150 155 160  
 26 130 140 150 155 160  
 27 130 140 150 155 160  
 28 130 140 150 155 160

01-63246 041403171604 1577

~~DATE 03/27/44.~~  
TIME 12.31.53.

~~WATERGATE - 12-19-74~~

NEW ENGLAND DIVISION - CORPS OF ENGINEERS

DAY	IN4	ININ	METRC	IPLT	IPRT	INSTAN
0	0	0	0	0	-4	0
5	0	0	0	0		

~~NO INFO~~ ~~1155~~ ~~1-10~~

ROUTED OUTFLOW FROM SCITTICO NAW

CLASS	CLASS	AVG	INES	ISAME	IUPI	IPMP	LSTR
0.0	0.000	0.00	1	1	0	0	0

STAGE-DISCHARGE DATA  
FOR SUTTCO DAM

SURFACE AREA				STAGE - STORAGE DATA	
	η.	7.	28.	77.	248.
CAPACITY	0.	51.	04.	519.	3703.
FOR QUITS DAM					

	CREL	SPLID	COGW	EIPW	FLEVL	COOL	CANEA	EXPL
→ SULLYWAY CRIST ELEVATION →	39.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

BREACH DATA - FAILURE BEGINS IMMEDIATELY  
 WITH RESERVING SURGEON AT GALLERY EAST

DAM BREACH DATA				
BRVID	PCNT	IPAIL	WSPL	PATLFL
76.	.01	114.00	.50	130.00
				130.00

**UNITED COMPUTING SYSTEMS, INC.**

PEAK OUTFLOW IS 7267 AT TIME 0.22 MINIMS  
BEAR SPRING DISCHARGE

# **BREACH FLOOD ROUTED TO DAMAGE CENTER**

SECTION DAM BREACH TO MAZARI AREA

STAU MAZARI	ICOMP	IFCON	ITYPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
0	1	0	0	0	0	1	0	0
CLASS	CLASS	AVG	INES	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSIPS	NSIDL	LAG	APSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-1.	0	

CHANNEL CHARACTERISTICS AT  
DAMAGE CENTER

Q (1)	Q (2)	Q (3)	FLVIT	FLMAX	MLNTH	SFL	CHANNEL CHARACTERISTICS AT DAMAGE CENTER
0.00	150.00	200.00	100.00	150.00	1350.	0.01000	DOWNSTREAM DAMAGE CENTER
0.00	100.00	100.00	100.00	100.00	150.00		

STREAMBED ELEVATION AT SECONDARY  
DAMAGE CENTER

STORAGE	0.00	4.21	9.14	20.83	65.59	134.47	194.50	269.08	342.20
OUTFLOW	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53
STAGE	103.00	107.47	107.47	110.42	112.49	117.44	120.32	122.79	125.26
FLOW	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53	227214.53
MAXIMUM STAGE IS	106.6	106.6	106.6	106.6	106.6	106.6	106.6	106.6	106.6

ELEVATION OF BREACH FLOODWATERS AT SECONDARY DAMAGE CENTER

106.6

# SOTTO DAM BREACH FLOOD RESULTS

## SUMMARY OF DAM SAFETY ANALYSIS

ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
51.	138.00	138.00	138.00
51.	51.	51.	51.

RATIO OF PAF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.00	0.00	51.	2247.	0.00	.22	0.00

PEAK BREACH OUTFLOW

## PLAN 1 STATION HAZARD

RATIO	MAXIMUM FLOW CFS	MAXIMUM STAGE FT	TIME HOURS
0.00	2044.	106.4	.17

PEAK BREACH  
FLOW AT DAMAGE CENTER

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

**END**

**FILMED**

**9-84**

**DTIC**